CHERDILLA

## U.S. DEPARTMENT OF LABO. Occupational Safety and Health Administration

Form Approved OMB No. 44-R1387

## MATERIAL SAFETY DATA SHEET OPM 1346-2

Required under USDL Safety and Health Regulations for Ship Repairing, Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)

	SECTION I		
MANUFACTURER'S NAME Cadillac Plastic and Chemical Co.		EMERGENCY TELEPHONE NO 616/343-1341	).
ADDRESS (Number, Street, City, State, and ZIP Code) 148 Parkway, Kalamazoo, Michigan	49006		
CHEMICAL NAME AND SYNONYMS		PS-18 Comp B	.14
Organic Peroxide Mixture	FORMUL	^(C <sub>6</sub> H <sub>5</sub> CO) <sub>2</sub> O <sub>2</sub>	

SECTIO	11 11 -		RDOUS INGREDIENTS	1	T. 7. 1
PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS N/A			BASE METAL N/A		
CATALYST			ALLOYS		•
VEHICLE			METALLIC COATINGS		
SOLVENTS			FILLER METAL PLUS COATING OR CORE FLUX		
ADDITIVES	ŀ		OTHERS		
OTHERS					
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES					TLV (Units)
Benzoy Peroxide				50	5 mg/m
DiCyclo Hexyl Phthalate	<del> :</del>			50	

	SECTION III -	PHYSICAL DATA
BOILING POINT (°F.)	N/A	SPECIFIC GRAVITY (H <sub>2</sub> O=1)
VAPOR PRESSURE (mm Hg.)	N/A	PERCENT, VOLATILE BY VOLUME (%)
VAPOR DENSITY (AIR=1)	N/A	EVAPORATION RATE ( =1)
SOLUBILITY IN WATER	Insol.	
APPEARANCE AND ODOR	White granules w	with slight odor.

SECTION IV - FIRE AND EXPLOSION HA		
FLASH POINT (Method used) , N/A , FLAMMABLE L	IMITS N/A	Uel
EXTINGUISHING MEDIA	in the second	£ 1 1 2 5 5
Small fires - water, foam, or CO2. Large fires - ev.	acuate area and ke	ep peroxide
we	t and cool.	
UNUSUAL FIRE AND EXPLOSION HAZARDS  May be ignited by contamination with strong exidizing o	r reducing agents,	including
polymerization accelerators.		

SECT JN V - HEALTH HAZARD DATA
THRESHOLD LIMIT VALUE 5 mg/m <sup>3</sup> pure benzoyl peroxide
EFFECTS OF OVEREXPOSURE
EMERGENCY AND FIRST AID PROCEDURES In case of contact with skin, wash with soap and water. In case of contact with
eyes, wash with copious quantities of water and consult physician. If ingested,
induce vomiting and consult a physician immediately.

Store below	UNSTABLE		conditions to Avoid Heat, sparks, open flame and direct		
80 deg F	STABLE	Х	sunlight.		
HAZABOUS DECO	·		2. 70 2 7 3.		
Bipnenyi	-toxic and i	lammab			
			I CONDITIONS TO AVOID		
HAZARDOUS POLYMERIZATION	MAY OCC	UR			

SECTION VII - SPILL OR LEAK PROCEDURES
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED
Wash any skin areas contacted.
WASTE DISPOSAL METHOD Using a non-sparking shovel, deposit peroxide in small shallow piles on several
sheets of newspaper. Ignite with torch having six-foot handle and back away.
Do not burn more than one pound at a time.

	SECTION VIII - SPEC	IAL PROTECTION	INFORMATION	
RESPIRATORY PI	ROTECTION (Specify type)			
VENTILATION	LOCAL EXHAUST		SPECIAL	
	MECHANICAL (General)		OTHER	
PROTECTIVE GLOVES Recommended		EYE PROTECT	ION	
OTHER PROTECT	IVE EQUIPMENT			

## SECTION IX - SPECIAL PRECAUTIONS

Use only with inert, noncontaminating materials. Polyethylene, stainless steel, teflon, or nylon are generally suitable. Do not use with materials susceptible to other precautions. Do not have in work area, more material than may be used in one production shift.

PAGE (2) 6P.0 930-540 Form OSHA-20